# DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt Governor Kathleen Clarke

**Executive Director** Lowell P. Braxton Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)



Partial XX	X Complete _	Expl	oration
Inspection Date:	06/21/2002/	Time: <u>1</u>	3:00 - 15:30
	ate of Last Ins		

Mine Name: Crandall Canyon Mine	County: Emery	Permit Number: <u>C/015/032</u>					
Permittee and/or Operator's Name: Genwal Resources, Inc.							
Business Address: P.O. Box 1077, Price, Utah 84501							
Company Official(s): Gary Gray							
State Official(s): Karl R. Houskeeper	Fed	Federal Official(s): None					
Weather Conditions: Clear, Temp 90 - 9	95°F						
Type of Mining Activity: Underground XXX Surface Prep Plant Other							
Existing Acreage: Permitted 5195.8 D	isturbed 10.7 Regrade	ed Seeded					
Status: Active							

## REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF	
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]	L.l			
2.	SIGNS AND MARKERS	[X]		[X]		
3.	TOPSOIL		ΞÌ			
4.	HYDROLOGIC BALANCE:					
a.	DIVERSIONS	[X]		[X]		
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]		[X]		
c.	OTHER SEDIMENT CONTROL MEASURES	[X]				
d.	WATER MONITORING	[X]		[X]		
e.	EFFLUENT LIMITATIONS	$\Box$				
5.	EXPLOSIVES			$\Box$		
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES					
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	$\Box$				
8.	NONCOAL WASTE	[X]		[X]		
9.	PROTECTION OF FISH, WILDLIFE AND RELATED					
	ENVIRONMENTAL ISSUES					
10.	SLIDES AND OTHER DAMAGE					
11.	CONTEMPORANEOUS RECLAMATION					
12.	BACKFILLING AND GRADING				Ļļ	
13.	REVEGETATION			$\Box$	Ļ	
14.	SUBSIDENCE CONTROL				لِـلِ	
15.	CESSATION OF OPERATIONS					
16.	ROADS:					
a.	CONSTRUCTION/MAINTENANCE/SURFACING					
b.	DRAINAGE CONTROLS			لِــاِ	لِـا	
17.	OTHER TRANSPORTATION FACILITIES			لِـلِ	لِــاِ	
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS				<u> </u>	
19.	AVS CHECK (4 <sup>th</sup> Quarter- April, May, June)		لِــالِ	<u> </u>	لِــا	
20.	AIR QUALITY PERMIT		لِسلِ	لمسل	<u></u>	
21	RONDING & INSURANCE	F 1	[ ]	1 1	1 1	

PERMIT NUMBER: <u>C/015/032</u> DATE OF INSPECTION: <u>06/21/2002</u>

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

#### 2. SIGNS AND MARKERS

Checked the ID sign at the entrance to the Mine site. The current address information has been added with a marker.

#### 4A. HYDROLOGIC BALANCE: DIVERSIONS

Spot checked the disturbed diversions and compared the MRP specifications with the diversions. DD-8 has been recently cleaned and meets the specifications listed in the MRP. The operator will seek clarification from the contracted engineer on a few of the diversions listed in the MRP.

### 4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sediment pond was viewed. Several sediment deltas exist in the pond especially at the inlet. The sediment level clean markers were visible and the current sediment level is below the top of the markers. The pond will continue to be monitored to determine when the pond needs to be cleaned.

#### 4D. HYDROLOGIC BALANCE: WATER MONITORING

Discussed the no access issues for water monitoring. Made the operator aware of the Division's position relative to no access. Mr. Gray indicated that attempts to modify monitoring plans in the past by reducing frequencies and/or taking samples to achieve four samples per year when access becomes available have not been accepted by Division personnel in the past. Further discussion on this issue will likely take place between the coal operator's environmental subcommittee.

The water monitoring was viewed on the EDI web site prior to the inspection. The water monitoring is current.

#### 8. NONCOAL WASTE

The mine site was viewed for noncoal waste. The site was clean and in good repair. Noncoal waste was present in the designated area and is being controlled prior to removal from the mine site.

Inspector's Signature:

Karl R. Houskeeper

Date: June 24, 2002

Note: This inspection

This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc:

James Fulton, OSM Gary Gray, Genwal

Price Field office

O:\015032.CRA\Compliance\2002\p\_0621.doc